

CLASSIFY TO FILE NO.

X-REF TO FILE NO.

FILE RID ☐ RET. TO BRANCH ☐

DESTROY ☐ SIG.

FROM

DISSEM BY 53

ACTION

LOGS

☐ RID COPY

ADVANCE COPY

☐ ISSUED ☐ SLOTTED ☐ TUBED

INFO

FILE, VR, FE

SECRET

GROUP 1
EXCLUDED FROM AUTOMATIC
DOWNGRADING AND
DECLASSIFICATION

REPRODUCTION PROHIBITED

PERSON/UNIT NOTIFIED

1		5	
2		6	
3		7	
4		8	

UNIT TIME BY

25X1A

25X1A

SECRET 040219Z CITE

LOGISTICS INFO DIRECTOR

ACTION

4 JUN 66 12 30709

25X1A

SENDS

25X1A

CAUSED BURN OUT ONE OF

TWO SINGLE PHASE REGULATORS. MUST REPLACE CORE SOONEST EST COST

25X1A

\$1500. STRONGLY RECOMMEND REPLACE

BOTH SINGLES WITH 3 PHASE REGULATOR MAINLY AS WE NOW NEAR NAMEPLATE

AMP RATING. EST COT \$9600. FUNDS ARE AVAILABLE. WOULD HOPE FOR

25X1A

PROCUREMENT OR SHIPMENT.

25X1A

DURING SAME PERIOD ONE 300 KW STANDBY GENERATOR ARCED OUT REQUIRING

25X1A

REBUILD WHICH WE CAN DO WITH SPARE PARTS ON HAND.

REQUEST RE AND CD EVALUATION

25X1A

ADVISABILITY PARA 1 PROPOSAL AND WOULD APPRECIATE

DETERMINE IF POSSIBLE TO UP RATE CATERPILLAR D-397 BY ENGINE

MODIFICATION AND INSTALLATION NEW HIGH TEMPERATURE GENERATOR

INSULATION. IF POSSIBLE WHAT COST. AM SURE YOU REALIZE WE NEED

EXPEDITIOUS REPLY WITH ONE GENERATOR DOWN AND ONLY ONE REGULATOR.

SECRET

BT

SECRET

C/REC
 2 DC/REC
 1 EDC
 C/ACQ
 3 C/OC
 4 C/UE
 29 July
 SEEN
 RTN +
 DBM
 CENTRAL FILE
 FILE